


09 Wall and ceiling luminaires

PLANELO RENEW

Quickinfo

LUMINAIRE

ceiling, wall
surface mounted
aluminium, white
IP40



LED

4000K
CRI>80
initial MacAdam 3 SDCM
50.000h L80

LIGHT DISTRIBUTION



ELECTRIC

ON-OFF switchable



-230 V
50-60Hz



IP
40



Description

PLANELO RENEW is the ideal solution for simple and efficient lighting refurbishment. As the latest addition to the PLANELO family, it has been specifically developed to replace existing surface-mounted luminaires with minimal effort. Thanks to its innovative mounting system and tailored dimensions, PLANELO RENEW enables a quick and clean upgrade, effortlessly covering traces left behind by previous installations. Additional work by painters or drywallers is typically unnecessary. Crafted using advanced aluminum profile technology, PLANELO RENEW offers the simplest and most cost-effective way to replace outdated T5/T8 surface-mounted grid luminaires – transforming spaces with modern LED performance and a clean aesthetic.



Types


PRODUCT CODE	POWER	LUMINOUS FLUX	COLOUR TEMP.	WEIGHT
LFPWQ18.1BC22	18W	2.100lm	3000K / 4000K selectable	2,0kg
LFPW044.1B422	44W	5.600lm	4000K	6,0kg

What's new:

New size, endless possibilities!


This series is expanding to include the **295x295mm** format. The integrated multicolor function now offers you even more flexibility.

Light distribution



MICROPRISM
UGR19-22


Dimension




Mounting system



Innovative fastening mechanism for simple and fast assembly




Multicolour



One luminaire, different colour temperatures

Selectable colour temperatures: 3000K/4000K

Optic



Microprism texture for decreased luminous intensity

CLEAN UPGRADE. NO COMPROMISE.



Dismantling of the old recessed grid luminaires with T5/T8 fluorescent tubes. Existing signs of use and wear, as well as aging-related color differences, become visible



PLANELO RENEW

Generous coverage of the existing mounting area. No ceiling repair work required.



Luminaire with standard market dimensions

Does not fully cover the existing mounting area – ceiling repairwork is necessary.